DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 99.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-020110 Address: 333 Burma Road **Date Inspected:** 07-Dec-2010

City: Oakland, CA 94607

OSM Arrival Time: 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

CWI Name: See Below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

Summary of Items Observed: On this date Caltrans OSM Quality Assurance (QA) Inspector Brett W Rice was present during the times noted above for observations relative to the work being performed at ZPMC.

Bay 14

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Fluxed Cored Arc Welding (FCAW) process.

ZPMC QC is identified as Wang Xian Pin.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

PCMK: AP-3031-001 Weld No: 246, 273 Welder: 052696

WPS-B-T-2133-ESAB

Volts: 25.7 Amps: 256

PCMK: AP-3031-001 Weld No: 218, 245 Welder: 055491

WPS-B-T-2133-ESAB

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Volts: 26.2 Amps: 263

PCMK: DP-3150-001 13CW

Weld No: 027~047 Welder: 205718

WPS-B-T-2132-ESAB

Volts: 25.4 Amps: 301

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Photos please see; Z:\Inspector Reports\B314 Rice

Summary of Conversations:

No relevant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Rice,Brett	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer